



WARRANTY INFORMATION

We sincerely thank you for your purchase and wish you years of pleasure using it!

Tele Vue Warranty Summary

Eyepieces, Barlows, Powermates, & Paracorr have a "Lifetime Limited" warranty, telescopes & accessories are warranted for 5 years. Electronic parts are warranted for 1 year. Warranty is against defects in material or workmanship. No other warranty is expressed or implied. No returns without prior authorization. Please keep your receipts in case you need warranty service.

Lifetime Limited Warranty details online: <http://bit.ly/TVOPTLIFE>

5-Year/1-Year Warranty details online: <http://bit.ly/TVOPTLIMITED>

Keep For Your Records

Dealer: _____ City/State/Country: _____

Date (day/month/year): ____/____/____ Item Code / Description _____

32 Elkay Dr., Chester, New York 10918 (845) 469-4551. televue.com



@televueoptics

(TLS-2245) Tubes and Spacers Set for 2.4"

This set includes 2 spacers and 4 Extension Tubes for 2.4" Imaging System accessories.

Parts List

- 0.040"/1mm spacer (TLF-0040)
- 0.080"/2mm spacer (TLG-0080)
- 0.250"/6.4mm tube (TLA-0250)
- 0.375"/9.5mm tube (TLB-0375)
- 0.500"/12.7mm tube (TLC-0500)
- 1.000"/25.4mm tube (TLD-1000)

Extension tubes thread together and into other threaded 2.4" Imaging System accessories. Spacers are non-threaded and are placed on the 2.4" accessory thread.



CAUTION: to avoid insufficient thread engagement, do not place more than one spacer between tubes. In the image here, the spacers are on either side of the 0.500" tube.

10/23/2009



32 Elkay Drive, Chester, New York 10918 845.469.4551 www.televue.com

(TLS-2245) Tubes and Spacers Set for 2.4"

This set includes 2 spacers and 4 Extension Tubes for 2.4" Imaging System accessories.

Parts List

- 0.040"/1mm spacer (TLF-0040)
- 0.080"/2mm spacer (TLG-0080)
- 0.250"/6.4mm tube (TLA-0250)
- 0.375"/9.5mm tube (TLB-0375)
- 0.500"/12.7mm tube (TLC-0500)
- 1.000"/25.4mm tube (TLD-1000)

Extension tubes thread together and into other threaded 2.4" Imaging System accessories. Spacers are non-threaded and are placed on the 2.4" accessory thread.



CAUTION: to avoid insufficient thread engagement, do not place more than one spacer between tubes. In the image here, the spacers are on either side of the 0.500" tube.

10/23/2009



32 Elkay Drive, Chester, New York 10918 845.469.4551 www.televue.com